



SERVICE REPORT

Report No: 010

Customer Name: IIL		
Address: IIL, Survey No: 281-284 & 321, Biotech park phase - III, Karakatta, Medak (Dist) - TS - 502281.		
BHT Ref No: BHT/HYD/20-21/SAR/0027		
Call Reported By: Chittaranjan	Date: 17-06-2021	Time: 4:00 PM
Contact Person: Chittaranjan	Designation:	Tel No: 9842512737
Type of Service: <input type="checkbox"/> Warranty <input checked="" type="checkbox"/> Maintenance <input type="checkbox"/> Chargeable Basis <input checked="" type="checkbox"/> Installation		
Technology Provider: Ruckus	Model: ICX 7150-48	Serial No: FEH3245R02H, M, R, G, E, B, N.
Problem Reported: New Installation		
Engineer Attended: H Sarveswara Rao	Date: 18-06-2021	Time In: 11:02 AM
Actual Fault: New Installation of Ruckus ICX 7150-48 - 7Nots		
Action Taken: Configuration has been done as per the customer requirement and checked by connecting to live network. And working fine.		
Status After Service: <input checked="" type="checkbox"/> Complete <input type="checkbox"/> Incomplete <input type="checkbox"/> Pending for spares <input type="checkbox"/> Under Observation		
Engineer Remarks:		
Customer Remarks:		
Engineer Signature:  Name: H Sarveswara Rao Date: 18-06-2021 Time Out: 4:30 PM	Customer Signature:  Name: K. CHITTARANJAN Designation: EXECUTIVE - IT Date: 18.6.21	