

SERVICE REPORT

DATE: 15/12/2023

CLIENT NAME: IIL

PLACE: TELANGANA

MACHINE SERIAL NO: 22242

MACHINE MODEL: COUNTER
REWINDER WITH
VVM APPLICATOR

TYPE OF SERVICE: INSTALLATION / CHARGEABLE / FREE / AMC

MAHARSHI ENGINEER NAME: AMST KUMAR BARK

REACHED DATE: 14/12/2023

LEFT DATE: 15/12/2023

CONTACT PERSON NAME	DESIGNATION	MOBILE NO
Mr. Wasim		

REPORT NOTES

Maharshi VVM DOT Machine Problems / Installation:

* PQ was pending.

Action Taken:

* PQ has been completed successfully.

* perform PQ as per PQ document.

* Training given to their packing team properly on Camera and Maharshi monitor as per their S.O.P.

* Machine is running fine. Result found satisfactory.

Trials taken at the speed of 600 VPM

Training for Maharshi counter rewinder vvm Machine has been given to all operators and concern people. Training has been given to following people.

1) _____ 2) _____ 3) _____

SERVICE REPORT

CLIENT REMARKS:

Handwritten: n/a

SERVICE ENGINEER REMARKS / SUGGESTIONS / OBSERVATIONS:

Handwritten: n/a

RECOMMENDED SPARES LIST:

Handwritten: n/a		

CONCLUSION

Maharshi service engineer has visited site. ~~Vm dot application~~ Machine is running and working satisfactory.

Signature

Handwritten signature
15-12-23

Signature

Signature

For Maharshi

Handwritten signature
15/12/2023



DAILY REPORT

DATE:- 14.12.2023

Maharshi's Engineer Name: Amit Kumar

Company Name: IIL

M/c No: 22242

Work Done:

- ~~* PQ Started.~~
- ~~* Training given as per Sor.~~
- ~~* Done documentation.~~
- ~~* Trail pending from IIL side.~~

FOR, _____
1. Vary.. 14.12.23
2. _____

FOR, MAHARSHI
1. Amit 14.12.23