

## Service Report

Date : 22 April 2022



<b>Company :</b>	INDIAN IMMUNOLOGICALS LIMITED GACHIBOWLI POST RAKSHAPURAM HYDERABAD 500032 INDIA	<b>Work Order No.:</b>	7000567097 ✓
<b>Contact Name:</b>	Rama Krishna	<b>Purchase Order No.:</b>	NA
<b>Contact Phone:</b>		<b>Service Address:</b>	SURVEY NO. 281-284 & 321 MEDAK 502281 INDIA
<b>Contact Email id:</b>	p.ramakrishna@indimmune.com		

WORK ORDER DETAILS		
Service Type	Serial Number	Registered Product Description
Installation / IQOQ	15832244	Flowstar IV Standard

### Items

Item/Po Item	Product	Description	Quantity	Field Service Engineer
10	PTS02QSFSTAR	Flowstar IQ/OQ at Site	1	Mohan Kurukundu
20	ISGLAB	FIELD LABOUR (HOURS)	6	Mohan Kurukundu

<b>Symptom Reported:</b>
None
<b>Problem Observed:</b>
None
<b>Service Performed:</b>
1. Completed the IQ/OQ of the instrument as per Document no GGFD0422 and found all test are passed satisfactory.2. Instrument and External Vent Valves are found working fine. 3. Hand Overed the Filled documents to customer.
<b>Verification:</b>
Date of Visits: 22nd April 2022

	22 April 2022		22 April 2022
Customer Signature:	Date	Engineer Signature: Mohan Kurukundu	Date