

**FIELD SERVICE REPORT**

**eppendorf**

Engineer's Name: B. SRIKANTH	S.S.R. No.: —	Date: —
Branch: HYDERABAD Mobile No.: 9121605485	W.o. No.: —	Date: —
E-mail: srikanth.b@eppendorf.co.in	Report Date: 05-04-2023	

No. of Day(s) worked: 01 From: 05-04-23 To: 05-04-23

Customer Address:	Instrument(s) Details:		
	Model	Serial No.	Version
Indian Immunologicals Ltd, R&D Lab, Rakshapuram, Gachibowli Hyderabad	Cryocube F440n	F440LK300	858

Attention: \_\_\_\_\_ Designation: \_\_\_\_\_  
 Phone: \_\_\_\_\_ Fax: \_\_\_\_\_ E-mail: \_\_\_\_\_

MATERIAL USED		
Part No.	Description	Quantity

Problem Reported: **IQ/OQ ACTIVITY**

Details of work done:  
 During visit unpacked the instrument and positioned at required location. 3pin top was changed, stabilizers is connected and power supply checked. Functional checks as per protocol completed and found Ok. Instrument is working fine.

Job Completed  
  Job Pending  
 Billing:  O/W  
 Warranty  
 AMC  
 Chargable

Action to be taken: —	Recommendation: —
-----------------------	-------------------

Customer Remarks:

Engineer's Signature <i>sn</i>	Customer's Signature with seal <i>M</i> 
-----------------------------------	--