

SERVICE REPORT

Our Ref. : <u>LCGC/Radweg/382/2022</u>	Engineer's Report No. <u>382</u>	Principals <u>LCGC</u>
Customer <u>M/S Indico Immunological</u>	Invoice Details : <u>—</u>	Activity
Address <u>Ud</u>	Instrument Details : <u>Topload</u>	Installation : <input checked="" type="checkbox"/>
<u>Rakshapuram, Gachi bouli</u>	Model : <u>PS 6100-R2M</u>	Warranty : <input type="checkbox"/>
Scientist <u>Ms. Dr. Y. Venugopal</u>	S.No.: <u>706500</u>	Contract : <input type="checkbox"/>
Phone <u>—</u> Fax <u>—</u> Telex <u>—</u>		Out of Warranty : <input type="checkbox"/>
		Billable : <input type="checkbox"/>

Work Details :

Installation

- * Installed the balance on AVT properly
- * Done internal & external Adjustment
- * Done QA / OQ / PQ Successfully
- * Explain about balance, working function to user and concern person
- * Balance is working in good condition

PARTS REPLACED

Part Number	Description	Quantity	Source	Amount
/	/	/	/	/

The service requested by us has been handled by Kranthi Kanti
Who visited us on 17/03/2022

He has carried out the above work to our satisfaction.
Customer Report : Balance was installed and working operation demonstrate.

Place : Gachi bouli Engineer Signature : [Signature] Customer Signature : [Signature]
Date : 17/03/2022 (with Seal) 17.03.2022