

SERVICE REPORT

Our Ref. : <u>LCGC/Roadway/381/2022</u>	Engineer's Report No. <u>381</u>	Principals <u>LCGC</u>
Customer <u>M/s Indian Immunological</u>	Invoice Details : <u>—</u>	Activity
Address <u>Itol.</u>	Instrument Details : <u>Top load</u>	Installation : <input checked="" type="checkbox"/>
<u>Rakshapuram, Gachibowli</u>		Warranty : <input type="checkbox"/>
Scientist <u>Mr. Dr. X. Venugopal</u>	Model : <u>PS2100.R2M</u>	Contract : <input type="checkbox"/>
Phone <u>—</u> Fax <u>—</u> Telex <u>—</u>	S.No.: <u>718566</u>	Out of Warranty : <input type="checkbox"/>
		Billable : <input type="checkbox"/>

Work Details :

Installation

- * Installation of Balance done on AVT
- * Done internal & external adjustment done successfully.
- * Done IQ / OQ / PQ Successfully
- * Explain about balance working function to user and concern person
- * Balance is working in good condition

PARTS REPLACED

Part Number	Description	Quantity	Source	Amount
/	/	/	/	/

The service requested by us has been handled by Kranthi Kumar
Who visited us on 18/03/2022

He has carried out the above work to our satisfaction.

Customer Report : Balance was installed, working demonstrated

Place : Gachibowli

Engineer Signature : [Signature]
18/03/2022

Customer Signature : [Signature]
(with Seal) 17.03.2022

Date : 18/03/2022