

# TECHSER POWER SOLUTIONS PVT. LTD.,

Flat-2, 1st Floor, Lakshminagar, Willington Road, Picket, **Secunderbad-500026.**  
Phone : 040-27804431, 32515236 E-mail : ap.service@techser.com  
**Head Office** : Customer Care No. : 9448990408 / 9448992177  
E-mail : service@techser.com



**INSTALLATION**  **SERVICE REPORT**

AP/ 20-21  
No.:

Date: 9/11/2020

Customer Address : Indian Immunologics Ltd,  
Gachibowli,  
Hyderabad.  
Contact Person : JVS Reddy  **CHARGEABLE**  
Contact No. : 9840395333  **AMC**  
 **GP**  
E-mail : \_\_\_\_\_  
Complaint Recd Date : \_\_\_\_\_ Time : \_\_\_\_\_ Complaint No / Indent No. \_\_\_\_\_

Unit Rating : 20kVA / 384V / 33 Ver : 3DS SL No : M42009077  
Unit Configuration : **SA / PRS / HSB / WITH LOGIC** UNIT GP : \_\_\_\_\_ Years  
Battery : AH : 42 Make : EXIDE No. of Batteries : 32  TUB  AUT  MFB  
Battery Configuration : **SA / PBB / CBB** BATT GP : \_\_\_\_\_ Years  
Accessories / Others : \_\_\_\_\_  
Nature of Complaint : New UPS Installation

INCOMING VOLTS : 1PH P-N : 245V N-E : 19V P-E : 246V  
3PH R-Y : 414V Y-B : 420V B-R : 422V N-E : 1.9V  
CHARGING VOLTAGE : 432V CHARGING CURRENT : \_\_\_\_\_ SA AT 330V  
INVERTER O / P VOLTAGE : 230V LOAD CURRENT : \_\_\_\_\_  
TYPE OF LOAD ON INVERTER: Computers : \_\_\_\_\_ Nos, Printers : \_\_\_\_\_  
Others : (Specify) \_\_\_\_\_

NATURE OF FAULT OBSERVED : I installed the new 20kVA online  
ACTION TAKEN : UPS and 12V 42AH EXIDE SMF Batteries  
(Remarks if Any) : 32 nos with stand. Now UPS working  
Condition fine on both mode with  
Load. O/P Voltage - RT- 399V, /B- 398V  
BR- 399V

This is to Certify that your Engineer Mr. O.B. THILAK / 7032669911  
has attended the installation / complaints and the system is working in good condition.  
Service Engineer Sign : [Signature]  
Date : 9/11/2020  
Time In : \_\_\_\_\_ Time Out : 18:00  
Customer's Sign. & Seal : [Signature]