

Sartorius Stedim India Pvt. Ltd.
 #69/2 & 69/3, Kunigal Road,
 Jakkasandra, Nelamangala,
 Bangalore 562123
 Phone: +9180 .68154177
 E-Mail: CustomerService.India@Sartorius-Stedim.com
Service Report: #5629



CUSTOMER	Additional Information
Customer No.: 20013554 Indian Immunologicals Limited (India) Rakshapuram, Gachibowli Post, Hyderabad 500032 India	PO No.: 4511004072 Service Contract: None Complaint No.: Type: Installation & Qualification Technician: Ayaaz Ahmed, Kunchala Srihari

SERVICE NOTES
<p>Installation and qualification for Sartocheck 5 Filter Tester 26787—FT As per schedule consignment check of Sartocheck 5 is completed. Physical appearance of the outer boxes is good and which are opened and sealed again. Sartocheck 5(s.no : 43701645)-01 no's, Inlet tube-01 no's, Outlet tube 01 no's, Sartocheck 5 Manual 01 no's, Calibration certificate for process and safety pressure sensors -01 no's of each, Quality assurance certificate -01 no's, power cable-01 no's,RJ45 cable-01 no's, Serial communication cable-01 no's, USB cable-01 no's, Torque Screw driver-01 no's USB mini 2.0 cable-01 no's, Printer-01 no's, printer power adaptor n cable-01 no's, printer manual -01 no's, Validation Document -01 no's, Barcode Scanner -01 no's, Stabuli-01 no's, Paper roll set (2 rolls, 1 cartridge and 1 back roll)-01 no's, Validation document is handover to customer.</p> <p>As per previous visit Sartocheck 5(41701781) consignment check verified Current visit Sartocheck 5 Installation and Qualification (IQ) completed as per approved protocol. Qualification document handover to user. Unit accessories are SC5 unit, inlet test tube, outlet test tube, power cable-01 No's, RJ45 cable-01 No's, Serial communication cable-01 No's, USB cable-01 No's, Torque Screwdriver-01 No's USB mini 2.0 cable-01 No's, YDP Printer-01 No's, printer power adaptor n cable-01 No's, Barcode Scanner -01 No's, Stabuli-01 No's, Paper roll set 1no (2nd role and cartridge both are along with printer).</p> <p>Unit working fine and satisfactory.</p> <p>Recommendation: Inlet pressure should be maintaining 6.5 bar. Inlet regulator should be arranging 0-10 bar range only not above range. Moisture trap required for inlet air connection. Don't bend the Inlet and outlet connections.</p> <p>Customer remarks: Please arrange user training for this system.</p> <p>Customer details Name: Mr. P. Suresh contact number:9908886785 Email id: psureshkumar@indimmune.com</p>

EQUIPMENT				
NAME	LOCATION	MFR.	MODEL NO.	SERIAL NO.
Sartocheck 5 Filter Tester	20013554		26787—FT	43701645

Labor				
Date	Item No.	Description	QTY	Comment
Feb 15, 2023	Travel Time	Travel hours	1.25	
Feb 15, 2023	Working Time	Labor hours	1.50	
Mar 27, 2023	Travel Time	Travel hours	3.00	Travel time
Mar 27, 2023	Working Time	Labor hours	7.00	Working hours
Mar 28, 2023	Travel Time	Travel hours	3.00	Travel time
Mar 28, 2023	Working Time	Labor hours	7.00	Working hours

Mar 29, 2023	Travel Time	Travel hours	1.50	Travel time
Mar 29, 2023	Working Time	Labor hours	3.00	Working hours

Material

Item No.	Description	QTY	Comment
----------	-------------	-----	---------

Expense Total

Date	Item No.	Description	QTY	Comment
------	----------	-------------	-----	---------

CUSTOMER NAME: (Suresh Kumar (D Manager))

Customer Signature



DATE Mar 29, 2023 @ 2:37pm

TECHNICIAN NAME: (Kunchala Srihari , Ayaz)

Technician Signature



DATE Mar 29, 2023 @ 2:37pm