

SERVICE REPORT

Our Ref. : <u>LCGC/Radweg/1504/2019</u>	Engineer's Report No. <u>104</u>	Principals <u>Radweg</u>
Customer <u>Indian Immunologies Ltd,</u>	invoice Details :	Activity
Address <u>Biotech park, Kallapattin</u>	Instrument Details : <u>precision</u>	Installation : <input type="checkbox"/>
Scientist <u>Sanjeev Kumar Dhal</u>	Model : <u>PS360.PL</u>	Warranty : <input checked="" type="checkbox"/>
Phone _____ Fax _____ Telex _____	S.No.: <u>621680</u>	Contract : <input type="checkbox"/>
		Out of Warranty : <input type="checkbox"/>
		Billable : <input type="checkbox"/>

Work Details :

- 1) Installation completed for balance with printer
- 2) given zero for uses
- 3) given 70.00 g for balances
- 4) The balance is working in good condition

PARTS REPLACED

Part Number	Description	Quantity	Source	Amount
/	/	/	/	/

The service requested by us has been handled by P. Rajeev
 Who visited us on 5/11/2019

He has carried out the above work to our satisfaction.

Customer Report :

Place : Kallapattin

Engineer Signature :

Customer Signature :
 (with Seal)

Date : 5/11/2019

Rajeev

[Signature]
 05.11.19