



Service Report

ROOTS
ADDING VALUE

CUSTOMER DETAILS :

Branch Name	HYD
Customer Name as per Invoice	Indian Immuno logical Ltd
Machine Location	Kulakapetta
Name of the Customer Representative	Mr. V. Sridhar
Customer Mobile Number	
Machine Model	E-430
Machine Serial Number	1279 40 94735
Hour Metre Reading	-

Service Ticket Number	Commissioning			
Machine Inspection Date	21-11-19			
Service Engineer Name	S. Navan Babu			
Visit Type	Warranty <input type="checkbox"/>	AMC/CAMC <input type="checkbox"/>	Paid visit <input type="checkbox"/>	Others <input type="checkbox"/>
	Maintenance <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Maintenance <input type="checkbox"/>	Commissioning <input checked="" type="checkbox"/>
	Repair <input type="checkbox"/>	Repair <input type="checkbox"/>	Repair <input type="checkbox"/>	Demo <input checked="" type="checkbox"/>
				Training <input type="checkbox"/>

CUSTOMER COMPLAINT DETAILS :

Machine Commissioning

OBSERVATION :

Machine suction not properly

ACTION TAKEN :

delivery time suction hose loose so tight the pipe now machine are working condition

CUSTOMER COMMENTS :

Demo has been given & machine working satisfactory. Training imparted to the concerned persons.

S. Navan Babu
7709996170
Signature of the Service Engineer

Shreeley.
Signature of the Customer

Roots Multiclean Ltd.

R.K.G. Industrial Estate, Ganapathy, Coimbatore - 641 006, India. Tel : +91 422 4330 321.
Email : rmcsales@rootsemal.com, Website : rootsmulticlean.com

Customer care: 1800-419-9779

Branch