

# FIELD SERVICE REPORT

# eppendorf

Engineer's Name: B. SRIKANTH	S.S.R. No.: —	Date: —
Branch: HYDERABAD Mobile No.: 9121605485	W.o. No.: —	Date: —
E-mail: srikanth.b@eppendorf.co.in	Report Date: 05-04-2023	

No. of Day(s) worked: 01 From: 05-04-23 To: 05-04-23

Customer Address:	Instrument(s) Details:		
	Model	Serial No.	Version
Indian Immunologicals Ltd, R&D Lab,	Cryocube	F440LG400632	
Rakshapuram, Gachibowli	F440n		
Hyderabad			

Attention: *P. Santhakumar* Designation: \_\_\_\_\_  
 Phone: 9951587652 Fax: \_\_\_\_\_ E-mail: \_\_\_\_\_

MATERIAL USED		
Part No.	Description	Quantity
/	/	/

Problem Reported: IQ/OQ ACTIVITY

Details of work done:  
 During visit unpacked the instrument and positioned at required location. 3pin top was changed, stabilizers is connected and power supply checked. Functional checks as per protocol completed and found Ok. Instrument is working fine.

Job Completed  
  Job Pending  
 Billing:  O/W  
  Warranty  
  AMC  
  Chargable

Action to be taken: —	Recommendation: —
-----------------------	-------------------

Customer Remarks:

Engineer's Signature <i>sn</i>	Customer's Signature with seal <i>P. Santhakumar</i>
-----------------------------------	---

**FIELD SERVICE REPORT****eppendorf**

Engineer's Name: B. SRIKANTH	S.S.R. No.: —	Date: —
Branch: HYDERABAD Mobile No.: 9121605485	W.o. No.: —	Date: —
E-mail: srikanth.b@eppendorf.co.in	Report Date: 05-04-2023	

No. of Day(s) worked: 01 From: 05-04-23 To: 05-04-23

Customer Address:	Instrument(s) Details:		
	Model	Serial No.	Version
Indian Immunologicals Ltd, R&D Lab,	Cryocube	F440LJ800	793
Rakshapuram, Gachibowli	F440n		
Hyderabad	IP: RED/Mot/Bu/ULF/80		

Attention: P. Santhakumar Designation: \_\_\_\_\_  
 Phone: 9951587605 Fax: \_\_\_\_\_ E-mail: \_\_\_\_\_

MATERIAL USED		
Part No.	Description	Quantity
/	/	/
/	/	/
/	/	/

Problem Reported: IQ/OQ ACTIVITY

Details of work done:  
 During visit unpacked the instrument and positioned at required location. 3pin top was changed, stabilizers is connected and power supply checked. Functional checks as per protocol completed and found Ok. Instrument is working fine.

Job Completed  
  Job Pending  
 Billing:  O/W  
 Warranty  
 AMC  
 Chargable

Action to be taken: — Recommendation: —

Customer Remarks:

Engineer's Signature: *[Signature]*      Customer's Signature with seal: P. *[Signature]*

# FIELD SERVICE REPORT

# eppendorf

Engineer's Name: B. SRIKANTH

S.S.R. No.: — Date: —

Branch: HYDERABAD Mobile No.: 9121605485

W.o. No.: — Date: —

E-mail: srikanth.b@eppendorf.co.in

Report Date: 05-04-2023

No. of Day(s) worked: 01 From: 05-04-23 To: 05-04-23

Customer Address:

Instrument(s) Details:

	Model	Serial No.	Version
Indian Immunologicals Ltd, R&D Lab,	Cryocube	F440LK300	858
Rakshapuram, Gachibowli	F440n		
Hyderabad			

Attention: DILLIKUMAR M

Designation:

Phone: 9160233033 Fax:

E-mail: m.dillikumar@indimmune.com

### MATERIAL USED

Part No.	Description	Quantity
/	/	/

Problem Reported:

IQ/OQ ACTIVITY

Details of work done:

During visit unpacked the instrument and positioned at required location. 3pin top was changed, stabilizers is connected and power supply checked. Functional checks as per protocol completed and found Ok. Instrument is working fine:

Job Completed  Job Pending Billing:  O/W  Warranty  AMC  Chargable

Action to be taken:

Recommendation:

Customer Remarks:

Engineer's Signature



Customer's Signature with seal



service@eppendorf.co.in • www.eppendorf.co.in

# FIELD SERVICE REPORT

# eppendorf

Engineer's Name: B. SRIKANTH	S.S.R. No.: —	Date: —
Branch: HYDERABAD Mobile No.: 9121605485	W.o. No.: —	Date: —
E-mail: srikanth.b@eppendorf.co.in	Report Date: 05-04-2023	

No. of Day(s) worked: 01 From: 05-04-23 To: 05-04-23

Customer Address:	Instrument(s) Details:		
	Model	Serial No.	Version
Indian Immunologicals Ltd, R&D Lab,	Cryocube	F440LJ400800	
Rakshapuram, Gachibowli	F440n		
Hyderabad	ID:	RED/vv1R/ULF/026	

Attention: Mv. Praveen. Designation: \_\_\_\_\_  
 Phone: 9030465523 Fax: \_\_\_\_\_ E-mail: \_\_\_\_\_

MATERIAL USED		
Part No.	Description	Quantity
/	/	/
/	/	/
/	/	/

Problem Reported: **IQ/OQ ACTIVITY**

Details of work done:  
 During visit unpacked the instrument and positioned at required location. 3pin top was changed, stabilizers is connected and power supply checked. Functional checks as per protocol completed and found Ok. Instrument is working fine.

Job Completed  
  Job Pending  
 Billing:  O/W  
 Warranty  
 AMC  
 Chargable

Action to be taken: — Recommendation: —

Customer Remarks:

Engineer's Signature: *sn*      Customer's Signature with seal: *Praveen 03/05/2023*