



# Field Service Report

Service Request # 3958670  
 Request Type ABSX Install  
 Service Start Date 10/03/2018 10:00  
 Service End Date 10/03/2018 12:00

Sciex,  
 A Div of DHR Holding India Pvt Ltd,  
 6-3-1239/2, 4th Floor, Amar House,  
 Raj Bhavan Road, Somajiguda,  
 Hyderabad – 500082, India  
 T: +91 40 4914 5650 | Fax : +91 40 4914 5677  
 HO : 121, Udyog Vihar, Phase-4,  
 Gurgaon, Haryana-122015, India

Customer Contact Information			
Customer Name	Indian Immunologicals Ltd	Contact Name	Satheesh P
Incident Address	Lingampally X Road, Near Stadium, Gachibowli Post, , Hyderabad, Telangana 500032, India	Phone	+91 7095005444.
		Email	p.satheesh@indimmune.com
		Customer PO#	
Problem Summary	Installation PA800 plus instrument		

Install Base Information		Contract Information	
Model	PA 800 plus	Contract	
Serial	A746032150	Contract Start Date	
Item	A74603	Contract End Date	
Item Instance	11559220	Coverage Type	ABSX WARRANTY
		Coverage Description	

Work Description
Complaint: Installation of PA800 plus Cause: New Installation Corrective Action: Checked the power supply and done the installation as per the protocol Software Version: 32karat 10.1 Service Guide: 144867AE

Task Type	Service Labor Activity	Engineer	Date	Duration	UOM
Installation	CE Non-billable Labor	Reddy, Satish	10/03/2018 10:00	2	HR
Installation	CE Non-billable Travel	Reddy, Satish	09/03/2018 09:00	1	HR
Installation	CE Non-billable Travel	Reddy, Satish	09/03/2018 18:00	1	HR

Item	Item Description	Quantity	UOM

Customer acknowledgement of above mentioned Service

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Technician: Reddy Satish

FSE Signature: \_\_\_\_\_

Date: \_\_\_\_\_

THIS IS NOT AN INVOICE!