




### INSTALLATION REPORT

CUSTOMER NAME : <i>Indian Immunological's Ltd.</i>		
SL NO : <i>OS/PL/MF8/74/SSPV-01</i>	EQUIPMENT NAME : <i>20L pressure vessel</i>	SERVICE ENGINEER NAME : <i>B. MURTHY</i>

NATURE OF VISIT : INSTALLATION     WARRANTY     OUT OF WARRANTY

DETAILS OF WORK :
<i>Visited Customer Site, unpacked Supplied Equipment</i>
<i>performed all the related tests Found OK.</i>
<i>provided All the related Certificates to Customer.</i>
<i>All the Calibration Certificates &amp; Components Certificates provided to Customer.</i>
<i>NA</i>

**Omega Scientific Instruments Pvt Ltd**  
 # 20, Rukmini Apt. Road, 3rd Main,  
 New BEL Road, RMV II Stage, Bangalore - 560 094.  
 Ph.: +91- 080 2341 6613/14, 2351 6612  
 Fax: +91 080 23516613, www.omegascientific.in  
 e-mail : info@omegascientific.in



# OMEGA

SCIENTIFIC INSTRUMENTS CUSTOMER REMARKS : ( IF ANY )

on site only pressure leak test performed.  
at 1.5 kg/cm<sup>2</sup> for 30 minutes

Swamy  
17-02-20 NA

SERVICE ENGINEER SIGNATURE & DATE :

A. Swamy  
17-02-2020

CUSTOMER SIGNATURE & DATE :

NAME	DEPARTMENT	DESIGNATION	SIGNATURE & DATE
P. Sudhakar Reddy	production	SI Executive	Swamy 17-02-20
P. Veera Sidda Reddy	Engineering	DY. Manager	Swamy 17-02-20
S. Srikanth	QA - Validation	Dy. Manager	Srikanth 17-02-20

Omega Scientific Instruments Pvt Ltd  
# 20, Rukmini Apt. Road, 3rd Main,  
New BEL Road, RMV II Stage, Bangalore - 560 094.  
Ph.: +91- 080 2341 6613/14, 2351 6612  
Fax: +91 080 23516613, www.omegascientific.in  
e-mail : info@omegascientific.in