




HALLY INSTRUMENTS


Manufacturer & Supplier of Laboratory Equipments

112, Vasupujya Industrial Estate, Laxmi Nagar, Opp. Laxmi Industrial Estate,
Off. Link Road, Goregaon (W), Mumbai - 400 104.
Tel : +91 22 2876 9190 / 2877 7670 / 8369229840
email: hallyinstruments2006@gmail.com • www.hally.in

VISIT / SERVICE REPORT

M/s. <u>Indian Immunologicals Limited</u>	Date : <u>27.12.2019</u>
Address : <u>Rakshapuram, Gachibowli post, Hyderabad - 500032</u>	Service Report No. <u>585</u>
Tel.:	Type of Visit / Job:-
E-mail Id: <u>psureshkumar@indimmune.com</u>	P. O. No.
C. Person : <u>Mr. Sureshkumar / Mr. Parah</u>	<input checked="" type="checkbox"/> Installation & Demonstration
Department : <u>production</u>	<input type="checkbox"/> Inspection <input type="checkbox"/> Repairs / Service
Instrument : <u>Leak Test apparatus</u>	<input type="checkbox"/> Annual Maintenance Contract (AMC)
Model No.: <u>MLT-03</u>	Serial No.: <u>018019</u>
Symptoms : <u>—</u>	If AMC, then visit no.
Action Taken : <u>Installation, operation & performance qualifications performed on site with documentation & printouts. Operations & maintainance explained to user. Calibration & performance test carried out for vacuum & time parameters.</u>	
Engineer's Remarks : <u>Leak test apparatus is working satisfactory.</u>	
Customer's Remarks : <u>Ta, Oa, Pa completed successfully.</u>	
For Hally Instruments Mob: 8356072693	
Customer's Signature	


27.12.2019
Tushar Chavan

 27.12.19
Customer's Signature