



# HALLY INSTRUMENTS

Manufacturer & Supplier of Laboratory Equipments

112, Vasupujya Industrial Estate, Laxmi Nagar, Opp. Laxmi Industrial Estate,  
Off. Link Road, Goregaon (W), Mumbai - 400 104.  
Tel : +91 22 2876 9190 / 2877 7670 / 8369229840  
email: hallyinstruments2006@gmail.com • www.hally.in

## VISIT / SERVICE REPORT


M/s. <u>Indian Immunological Limited</u>	Date: <u>09/02/2021</u>
Address: <u>Rakshapur, Gachibowli</u> <u>Post - Hyderabad, 500032.</u>	Service Report No. <b>1001</b>
Tel.:	Type of Visit / Job:-
E-mail Id:	P. O. No. <u>451100337</u>
C. Person: <u>Mr. Pawana Narsimhulu</u>	<input checked="" type="checkbox"/> Installation & Demonstration
Department: <u>Production</u>	<input type="checkbox"/> Inspection <input type="checkbox"/> Repairs / Service
	<input type="checkbox"/> Annual Maintenance Contract (AMC)
	If AMC, then visit no.


Instrument: <u>Leak Test Apparatus (HLT-03)</u>	Serial No.: <u>000066</u>
Model No.: <u>HLT-03</u>	
Symptoms: <u>Installation &amp; Demonstration</u>	

Action Taken: IQ, OQ & PQ performed on site machine  
successfully installed, Operation & general maintenance  
explained to user. PQ completed with test prints attached.  
with documents one calibration kit is provided with  
machine

Engineer's Remarks: Leak Test Apparatus is working OK.

Customer's Remarks: OK

  
09/02/2021  
For Hally Instruments

  
09.02.21  
Customer's Signature