



LABMATE (ASIA) PVT. LTD.

BAID MEHTA COMPLEX, C- BLOCK, 1ST FLOOR,
 NO 16 (OLD NO.183), MOUNT ROAD, SAIDAPET, CHENNAI - 15. INDIA.
 TEL : 044-2220 0066 / 2220 0166
 E-mail : customersupport@labmateasia.com / sales@labmateasia.com
 Website : www.labmateasia.com

Customer Copy

Office Copy

INSTALLATION / SERVICE REPORT

| | |
|---|--|
| Customer : <u>ILL</u> | Product : <u>Euromax microscope</u> |
| Address : <u>Gachibowli, Hyderabad.</u> | Serial No. : <u>EU2210586</u> |
| | Model : <u>i-scope</u> S.W. Ver. |
| Contact Person : <u>E-Venkat Reddy</u> | Date(s) of Visit : <u>11/11/22</u> |
| Phone : <u>9705652221</u> Fax : | Job Completed : Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| Department : <u>Production</u> | Reasons For <input checked="" type="checkbox"/> Installation <input type="checkbox"/> Warranty <input type="checkbox"/> Service Contract <input type="checkbox"/> Paid Service |
| | Visit <input type="checkbox"/> Free Service <input type="checkbox"/> Inspection <input type="checkbox"/> Customer Training <input type="checkbox"/> Others |

Description of Works Installation.

- ① Unpacked the instrument and found no damages during transportation.
- ② Shifted the instrument to the lab and installed on sturdy table.
- ③ Assembled all the lenses and the parts given 230V AC power supply to the instrument.
- ④ checked the all magnification lenses with slide and found good.
- ⑤ Given demo to the user and instrument overall working performance is satisfactory.

6) installation completed & found ok.

| | |
|-------------------------------------|--------------------------------|
| <u>EVR Reddy</u> <u>11-11-22</u> | <u>Pran</u> <u>11/11/22</u> |
|-------------------------------------|--------------------------------|

Customer's Signature & Seal Date : Engineer's Signature Date :

Customer Name : E. Venkat Reddy