

Unit no. 213, 2nd Floor, A-Block,  
My Home Tycoon Building, Begumpet,  
Hyderabad-500016.



Phone : (040) 4241 4328  
Fax : (040) 4241 4327  
e-mail : hyd @ toshvin.com  
Web. : www.toshvin.com

**SERVICE REPORT**

Customer : <b>Indian Immunologicals Limited</b>	Product : <b>Shimadzu UV-Visible Spectrophotometer</b>
Contact : <b>Mrs.Lakshmi Tulasi</b>	Model No <b>UV-19001</b> Sr. No. <b>A12535880494</b>
Dept : <b>Production</b>	Arrival Date <b>23/ 07/ 2021</b> Dep. Date : <b>27/ 07/ 2021</b>
Address & : <b>Gachibowli</b>	Time In : <b>14:30</b> Time Out : <b>14:00</b> Total Days : <b>3 Days</b>
Tel No. : <b>8019268656</b>	Service Contract Visit No. <b>1</b> Revisit Required: <input type="checkbox"/> Y / <input checked="" type="checkbox"/> N
Fax No. : <b>.</b>	Date of Revisit Committed : <b>Nil</b>
E-mail : <b>'lakshmitulasi@indimmune.com'</b>	Product working satisfactory <input checked="" type="checkbox"/> Yes      Send to Service Div. <input type="checkbox"/> Beyond Repairs <input type="checkbox"/>
<b>SYMPTOM:</b>	<b>REPAIR ACTION :</b>
<b>UV-19001 Installation and Qualification</b>	Checked the Installation site,found ok.Installed the Instrument&Performed Qualification to the Instrument.Found results satisfactorily.Documented the results and handed over to the customer.Demonstration given to the users on Instrument Operation.
<b>P.O No: 4511003380</b>	
<b>PO Date: 02/11/2020</b>	
<b>Customer's Remarks</b>	<b>ACTION REQUIRED BY :</b>
<b>Installation completed</b>	Customer <input type="checkbox"/> Engineer <input type="checkbox"/>
<b>Training has been completed</b>	N/A      N/A
Consumed	Components To be Identified
NA	NA
Source	NA
Service Engineer's Name <b>K.K.Sreenivasulu&amp;Ravi Talla</b>	Work accepted by <b>K. Lakshmi Quasar</b>
Signature <b>Ravi Talla</b> <b>K. Ravi</b> <b>27-07-2021</b> <b>(2291950745)</b>	Signature <b>K. Ravi</b> <b>27.07.21</b> <b>Deputy Manager</b>