



AR SYSTEMS

27A/15A, Thiruvalluvar Salai Junction, K.B. Dhasan Road,
Teynampet, Chennai-600 018. ☎: 9597633732
E-mail: advancedrefrigeration2012@gmail.com



turn to the exports

Commissioning SERVICE REPORT

Date : _____		Job No. : 089		Date : 01.05.18			
Complaint No. : _____		Complaint Time : _____		Reporting Time : _____			
Complaint Time : _____		Reporting Time : _____		Completion Time : _____			
Client H's Human Biologicals Institute Ooty			Natural of Complaint Installation of new Cold room of Refrigeration unit				
Natural of Service Warranty <input type="checkbox"/> AMC <input type="checkbox"/> Chargeable <input type="checkbox"/> Equipment : CR <input type="checkbox"/> CB <input type="checkbox"/> MD <input type="checkbox"/> Cond. Sl. No. G.R.P 0003010 Evap. Sl. No. _____ Com. Model : CP42 Com. Sl. No. WPA 0080083 Air Cooled Cond. <input checked="" type="checkbox"/> Water Cooled Cond. <input type="checkbox"/>			Brief Report of Inspection Installed the unit and Cold room, then covering shed.				
Voltage : RY 408 YB 408 BR 408			Amp. Temp. : _____				
RT°C	SP	DP	OP	1MP	Comp A	Cond A	Evap A
-18°C	4°C	17.5°C	18	18	R 6.0	1.0	1.2
					Y 6.0		
					B 6.0		
Evaporator Temperature		Condenser Temperature		Compressor Oil		Liquid Indicator	
In	Out	In	Out	Level		Level	
+2°C	+2°C	+18°C	+22°C	18		18	
HP		LP		Thermostat		Nos.	
						Amps	
Cut in	24mm	55mm	+5°C	Coil Heater		/	
Cut Out	30mm	25mm	+9°C	Tray Heater		/	
				Drain Heater		/	
Service Rendered : New unit installed and Commissioned. New unit working properly. Including covering shed as per requirement.							
Material Used				<input type="checkbox"/> Chargeable		<input type="checkbox"/> Non Chargeable	
Technician Remarks : Name : N. Isala				Customer's Remarks : Cold room installation work and shed work complete with our required mat. cold room runs condition normally. Signature with Seal Name : P. Suresh			