


PMS checklist [Julabo]

Date & Time	10/03/2025 03:15 PM
Periodical Maintenance	
JULABO Model	Daihan HPLP-C-R-Set, 350°C Large Plate Hotplate Digital with remote controller, 310 X 620 mm , 230 V / 50 Hz
Serial No	0400997165P007
Barcode No	0400997165P007
A) Complete physical check:	
1) Is there any damage on the unit ?	Yes
2) Is the bath tank clean?	No
3) Is there cooling control cable ok and moisture free?	No
4) Is the bath fluid in good condition?	No
5) Is the tubing, Insulation & clamp all ok?	No
6) Is the circulation pump motor noise free ?	No
7) Are all screws are intact and good condition?	No
Cooling /Heating & control function check :	
1) can unit cool down?	No
2) Can the unit is heating up?	No
3) Can set point Temperature maintained?	No
Refrigeration System check:	
Refrigeration System check	Yes
1) clean chill water strainer (for water-cooled unit)	Yes
2) clean air condenser fins (for air cooled system)	No
3) check for any corrosion in all parts of system	No
4) Ensure all mounting bolts and nuts are tight	Yes
5) check condenser fan motor is free	No

of movement	
6) check condenser fan motor is noise free	No
7) check for copper pipes vibration and noise	Yes
8) Any ice formation on compressor /parts	Yes
9) Ensure solenoid valve s moisture /corrosion free	No
10) Ensure insulation in good condition	No
11) clean on internal and external of unit	No
12) Cross check the unit temperature with calibrated thermo meter?	Yes
Performed by	Parchuri Bhuvana Chandra Shekhara K

SERVICE REPORT

Zuper ID No:	2409		
Company	Indian Immunologicals Ltd.		
Company Address	Indian Immunologicals Colony, Hyderabad Telangana 500032		
User Name	Ms. Anitha Reddy .		
Designation	Manager		
Department	Human Health QC		
Mobile Number	7675854025		
Email	anithareddy@indimmune.com		
Principle	DAIHAN Scientific Co., Ltd.		
Model	Daihan HPLP-C-R-Set, 350°C Large Plate Hotplate Digital with remote controller, 310 X 620 mm , 230 V / 50 Hz		
Serial No.	0400997165P007		
Installation date	2025-03-10		
Joint Visit	Parchuri BhuvanaChandra		
Service Covered	SV (FOC)		
Description of Inspection	Heating is not working		
Description on analysis	Check the physical condition of the and ceramic plate is damaged later check the coil is damaged		
Description on Conclusion	considering the age and condition of unit we suggest of scrap it. ceramic plate cost more than half of the unit		
Quotation			
Total Time Spent	6		
SI No	Part No	Model/Description	Qty
Name of the Application	heating of vaccines and water samples		
Engg. Remarks:	we suggest the customer scrap the unit		
Engineer Name	Parchuri Bhuvana Chandra Shekhara K		
Engineer Email	bhuvana.chandra@srico-labworld.com shekara.reddy@srico-labworld.in		
Engineer Phone Number	7093001339 8618794320		
Engineer Signature			

Customer Name	Tarun
Customer Signature	
Customer Remarks	